



# DOUBLE DETECTOR CHECK VALVE ASSEMBLY DETAIL

REVISIONS:

DATE

APPROVED:  
FEB. 2002

PAGE No.

800-16

**NOTE:**

**A.** ALL BACKFLOW PREVENTION ASSEMBLIES SHALL BE DELIVERED FOR INSTALLATION COMPLETELY ASSEMBLED BY THE ORIGINAL MANUFACTURER WITH ALL COMPONENTS AS APPROVED.

**B.** CLASS 53 DUCTILE IRON TO VALVE. ALL JOINTS RESTRAINED.

