



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 01/30/19

Facility name: City of Sidney

Ohio NPDES permit no.: 1PD00009*QD

Period covered by report: 2018

Contact person

Name: Stephen S Rhodes

Title: Underground Utilities Superintendent

Mailing address: 201 W Poplar Street
Sidney, Ohio 45365

Telephone: (037)498 - 8157

Email: srhodes@sidneyoh.com

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name Stephen S Rhodes

Title: Underground Utilities Superint

(typed): _____

Signature: _____

Date: _____

Enter narrative analysis of WIB patterns by location, frequency and cause.

Three of the WIB occurrences were due to the extreme weather on 04/03/18.
One occurrence was at Wendy's and due to heavy grease build-up. Approximately 4 gallons of wastewater backed up through a floor drain.
Two occurrences in sewershed S1-5 occurred on the same day due to roots and debris in the sanitary sewer main.
The occurrence in sewershed S1-8 was due to roots and debris in the sanitary sewer main.